

U.S. ENVIRONMENTAL PROTECTION AGENCY  
POLLUTION/SITUATION REPORT  
B&R Custom Chrome - Removal Polrep  
Initial Removal Polrep

US EPA RECORDS CENTER REGION 5



437506



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Region V

**Subject:** POLREP #1  
Initial POLREP  
B&R Custom Chrome  
  
Toledo, OH  
Latitude: 41.6562771 Longitude: -83.5830892

**To:** Sherry Fielding, U.S. EPA  
Jason El-Zein, U.S. EPA  
Sam Borries, U.S. EPA  
Ann Whelan, U.S. EPA  
John Glover, U.S. EPA  
Mark Durno, U.S. EPA  
Valencia Darby, Department of Interior  
Kevin Clouse, Ohio EPA  
Scott Shane, Ohio EPA  
Thomas Marks, U.S. EPA  
Carol Ropski, U.S. EPA  
Timothy Murphy, City of Toledo  
Michelle Tucker, TDES

**From:** Jon Gulch, On-Scene Coordinator

**Date:** 5/18/2012

**Reporting Period:** May 17-18, 2012

## 1. Introduction

### 1.1 Background

<b>Site Number:</b>	<b>Contract Number:</b>
<b>D.O. Number:</b>	<b>Action Memo Date:</b>
<b>Response Authority:</b> CERCLA	<b>Response Type:</b> Emergency
<b>Response Lead:</b> EPA	<b>Incident Category:</b> Removal Action
<b>NPL Status:</b> Non NPL	<b>Operable Unit:</b>
<b>Mobilization Date:</b> 5/17/2012	<b>Start Date:</b> 5/17/2012
<b>Demob Date:</b>	<b>Completion Date:</b>
<b>CERCLIS ID:</b>	<b>RCRIS ID:</b>
<b>ERNS No.:</b>	<b>State Notification:</b>
<b>FPN#:</b>	<b>Reimbursable Account #:</b>

#### 1.1.1 Incident Category

Emergency Response to an abandoned metal plating/polishing shop that was partially destroyed in a fire on May 16, 2012.

#### 1.1.2 Site Description

Large abandoned brick building with unobstructed access due to a partially demolished building.

##### 1.1.2.1 Location

The building is located at 1642 Oakwood (corner of Oakwood and Clinton) in Toledo, Lucas County, OH 43607.

##### 1.1.2.2 Description of Threat

Unobstructed access to totes and tanks of chemicals and fire damaged totes leaking chemicals to the loading dock.

#### 1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

No Access to the property. Site Assessment will be completed upon signature of access.

## 2. Current Activities

### 2.1 Operations Section

#### 2.1.1 Narrative

##### 2.1.2 Response Actions to Date

The EPA Emergency and Rapid Removal Service (ERRS) contractor was mobilized to the site to install a fence to limit access to the property.

##### 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

The enforcement team will work to identify the owner and/or operator of the site. Access will then be achieved for a Site Assessment.

#### 2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>


## **2.2 Planning Section**

### **2.2.1 Anticipated Activities**

- Install fence to limit access to the site
- Perform assessment on the totes and tanks
- Perform disposal of abandoned chemicals

#### **2.2.1.1 Planned Response Activities**

- Secure site
- Remove chemicals

#### **2.2.1.2 Next Steps**

- Obtain site access

### **2.2.2 Issues**

The current property owners are deceased and the property is in foreclosure. The EPA enforcement team will need to work to obtain written access to conduct the Site Assessment.

## **2.3 Logistics Section**

N/A

## **2.4 Finance Section**

### **2.4.1 Narrative**

N/A

## **2.5 Other Command Staff**

### **2.5.1 Safety Officer**

N/A

### **2.5.2 Liaison Officer**

N/A

### **2.5.3 Information Officer**

N/A

## **3. Participating Entities**

### **3.1 Unified Command**

N/A

### **3.2 Cooperating Agencies**

City of Toledo-Environmental Services

## **4. Personnel On Site**

EPA-1

## **5. Definition of Terms**

N/A

**6. Additional sources of information**

**6.1 Internet location of additional information/report**

N/A

**6.2 Reporting Schedule**

N/A

**7. Situational Reference Materials**

N/A